



**Keysight Network Packet Broker v5.3.0**

# **Common Criteria Guide**

**Version 1.0**

**June 2020**

**Document prepared by**



[www.lightshipsec.com](http://www.lightshipsec.com)

## Table of Contents

<b>1</b>	<b>About this Guide</b> .....	<b>3</b>
1.1	Overview .....	3
1.2	Audience .....	3
1.3	Terminology .....	3
1.4	About the Common Criteria Evaluation .....	3
1.5	Conventions .....	5
1.6	Related Documents .....	6
<b>2</b>	<b>Secure Acceptance and Update</b> .....	<b>7</b>
2.1	Obtaining the TOE .....	7
2.2	Verifying the TOE .....	7
2.3	Power-on Self-Tests .....	7
2.4	Updating the TOE .....	8
<b>3</b>	<b>Configuration Guidance</b> .....	<b>10</b>
3.1	Installation .....	10
3.2	Administration Interfaces .....	10
3.3	Cryptography.....	10
3.4	Default Passwords .....	10
3.5	Setting Time .....	11
3.6	Audit Logging .....	11
3.7	Administrator Authentication .....	11
3.8	TLS Communication .....	11
<b>Annex A:</b>	<b>Log Reference</b> .....	<b>13</b>
3.9	Format .....	13
3.10	Events .....	13

## List of Tables

Table 1:	Terminology .....	3
Table 2:	Evaluation Assumptions .....	5
Table 3:	Related Documents .....	6
Table 4:	Audit Events .....	13

# 1 About this Guide

## 1.1 Overview

- 1 This guide provides supplemental instructions to achieve the Common Criteria evaluated configuration of the Ixia, A Keysight Business Keysight Network Packet Broker v5.3.0 and related information.

## 1.2 Audience

- 2 This guide is intended for system administrators and the various stakeholders involved in the Common Criteria evaluation. It is assumed that readers will use this guide in conjunction with the related documents listed in Table 3.

## 1.3 Terminology

**Table 1: Terminology**

Term	Definition
AES	Advanced Encryption Standard
CRC	Cyclic Redundancy Check
DRBG	Deterministic Random Bit Generator
ECB	Electronic Codebook
HMAC	Hashed Message Authentication Code
KAT	Known Answer Test
NDRNG	Non-Deterministic Random Number Generator
NPB	Network Packet Broker
SHA	Secure Hash Algorithm
TOE	Target of Evaluation

## 1.4 About the Common Criteria Evaluation

- 3 The Common Criteria for Information Technology Security Evaluation (ISO/IEC 15408) is an international standard for security certification of IT products and systems. More information is available at <https://www.commoncriteriaportal.org/>

### 1.4.1 Protection Profile Conformance

- 4 The Common Criteria evaluation was performed against the requirements of the Network Device collaborative Protection Profile (NDcPP) v2.1 available at <https://www.niap-ccevs.org/Profile/PP.cfm>

### 1.4.2 Evaluated Software and Hardware

- 5 The Target of Evaluation (TOE) includes the Ixia Vision Series Network Packet Broker v5.3.0 software running on hardware appliances:

- Vision ONE
- Vision 7300/7303
- Vision E40
- Vision E100
- Vision E10S
- Vision X
- TradeVision

### 1.4.3 Evaluated Functions

- 6 The following functions have been evaluated under Common Criteria:

- **Protected Communications.** The TOE provides secure communication channels:
  - i) **Serial Console.** Administrative interface via direct serial connection.
  - ii) **GUI/Web API.** Administrative web GUI/Web API via HTTPS.
  - iii) **Logs.** Logs sent to syslog via TLS.
  - iv) **NTP.** NTP communications make use of SHA-1 message digests.
- **Secure Administration.** The TOE enables secure management of its security functions, including:
  - i) Administrator authentication with passwords
  - ii) Configurable password policies
  - iii) Role Based Access Control
  - iv) Access banners
  - v) Management of critical security functions and data
  - vi) Protection of cryptographic keys and passwords
- **Trusted Update.** The TOE ensures the authenticity and integrity of software updates through digital signatures.
- **System Monitoring.** The TOE generates logs of security relevant events. The TOE stores logs locally and is capable of sending log events to a remote audit server.
- **Self-Test.** The TOE performs a suite of self-tests to ensure the correct operation and enforcement of its security functions.
- **Cryptographic Operations.** The cryptographic algorithms used in the above functions have been validated for correct implementation.

7 **NOTE:** No claims are made regarding any other security functionality.

#### 1.4.4 Evaluation Assumptions

8 The following assumptions were made in performing the Common Criteria evaluation. The guidance shown in the table below should be followed to uphold these assumptions in the operational environment.

**Table 2: Evaluation Assumptions**

Assumption	Guidance
Physical security, commensurate with the value of the TOE and the data it contains, is provided by the environment.	Ensure that the device is hosted in a physically secure environment, such as a locked server room.
There are no general-purpose computing capabilities (e.g., compilers or user applications) available on the TOE, other than those services necessary for the operation, administration and support of the TOE.	Do not install other software on the device hardware.
The TOE does not provide any protection of traffic that traverses it. It is assumed that protection of this traffic will be covered by other security and assurance measures in the operational environment.	The Common Criteria evaluation focused on the management plane of the device.
Security Administrators are trusted to follow and apply all guidance documentation in a trusted manner.	Ensure that administrators are trustworthy – e.g. implement background checks or similar controls.
The TOE firmware and software is updated by an Administrator on a regular basis in response to the release of product updates due to known vulnerabilities.	Apply updates regularly according to your organization's policies.
The Administrator's credentials (private key) used to access the TOE must be protected on any other platform on which they reside.	Administrators should take care to not disclose credentials and ensure private keys are stored securely.
The Security Administrator ensures that there is no unauthorized access possible for sensitive residual information (e.g. cryptographic keys, keying material, PINs, passwords etc.) on networking equipment when the equipment is discarded or removed from its operational environment.	Administrators should sanitize the device before disposal or transfer out of the organization's control.

## 1.5 Conventions

9 The following conventions are used in this guide:

- CLI Command `<replaceable>` - This style indicates to you that you can type the word or phrase on the command line and press [Enter] to invoke a command. Text within `<>` is replaceable. For example:  
Use the `cat <filename>` command to view the contents of a file
- [key] or [key-combo] – key or key combination on the keyboard is shown in this style. For example:  
The [Ctrl]-[Alt]-[Backspace] key combination exits your graphical session and returns you to the graphical login screen or the console.
- **GUI => Reference** – denotes a sequence of GUI screen interactions. For example:  
Select **File => Save** to save the file.
- [REFERENCE] *Section* – denotes a document and section reference from Table 3. For example:  
Follow [USER] *Configuring Users* to add a new user.

## 1.6 Related Documents

10 This guide supplements the below documents which are available from <https://support.ixiacom.com>

**Table 3: Related Documents**

Reference	Document
[INSTALL]	<p>Please refer to the Installation Guide of your TOE device.</p> <p>Ixia Vision X Installation Guide, 913-2542-01 Rev A</p> <p>Ixia Vision 7300/7303 Network Packet Broker Installation Guide v5.2.0, 913-2530-01 Rev A</p> <p>Ixia Vision ONE Installation Guide, 913-2419-01 Rev B</p> <p>Ixia Vision Edge 40/100 Installation Guide, 913-2450-01 Rev A</p> <p>Ixia Vision Edge 10S Installation Guide, 913-2529-01 Rev A</p> <p>Ixia TradeVision Installation Guide, 913-2421-01 Rev A</p>
[USER]	<p>Please refer to the User Guide of your TOE device.</p> <p>Ixia Vision X User Guide v5.3.0, 913-2547-01 Rev B</p> <p>Ixia Vision 7300/7303 User Guide v5.3.0, 913-2548-01 Rev B</p> <p>Ixia Vision ONE User Guide v5.3.0, 913-2549-01 Rev B</p> <p>Ixia Vision Edge 40/100 User Guide v5.3.0, 913-2550-01 Rev B</p> <p>Ixia Vision Edge 10S User Guide v5.3.0, 913-2552-01 Rev B</p> <p>Ixia TradeVision User Guide v5.3.0, 913-2565-01 Rev B</p>

11 **NOTE:** The information in this guide supersedes related information in other documentation.

## 2 Secure Acceptance and Update

### 2.1 Obtaining the TOE

12 Your Ixia Network Packet Broker will be delivered via commercial courier. Perform the following checks upon receipt (return the device if either of the checks fail):

- Confirm that the correct device has been delivered
- Inspect the packaging to confirm that there are no signs of tampering

13 Follow instructions at [INSTALL] *Order of Installation and Setup* to setup the TOE.

### 2.2 Verifying the TOE

14 After logging in as a system administrator select **System > Version** to check current version of the software.

15 See section 2.4 below for the instructions on updating the TOE.

### 2.3 Power-on Self-Tests

16 On start-up, the system will run a series of self-tests:

- **POST.** The system runs Power-On diagnostic Self-Test (POST) every time it starts until disabled. Refer [USER] *Run POST tests and Get POST Results*.
- **FIPS Self-tests.** The TOE checks the integrity of the system files at the startup. See [USER] *Startup System Integrity Check* section of the *Government Configuration Guide* chapter.

17 The TOE runs FIPS-Approved power-up self-tests (during power-up or reboot of the TOE) and conditional self-tests. Refer [USER] *Enable Server FIPS Encryption* section of the *Government Configuration Guide* chapter. If any of the self-tests fail to produce the expected outcome, an error message indicating the failure and a timestamp of when the error occurred is written to the local logfile buffer, the module enters a critical error state, and the appliance shuts down.

18 The FIPS-Approved power-up and conditional self-test failures result in the following error message: FIPS self test failed as of <timestamp> with error: \$1.

19 The \$1 is a placeholder for an error that differs depending on the self-test. The error options are listed below for each self-test:

- AES -ECB KATs (Encryption/Decryption)
  - i) Failed self test on encryption: AES
  - ii) Failed self test on decryption: AES
- RSA KATs (Signature Generation/Signature Verification)
  - i) Self test signature generate failed.: RSA
  - ii) Self test signature verify failed.: RSA
  - iii) Self test SVE encryption KAT failed.: RSA/SVE
  - iv) Self test SVE decryption KAT failed.: RSA/SVE
  - v) Self test SVE failed.: RSA/SVE

- vi) Exception on self test: signing requires private key: RSA
- vii) Exception on self test: verification requires public key: RSA
- SHA -1 KAT
  - i) Self test failed : SHA-1
- SHA-256 KAT
  - i) Self test failed : SHA-256
- HMAC (with SHA-1) KAT
  - i) Self test failed : SHA-1/HMAC
- HMAC (with SHA-256) KAT
  - i) Self test failed : SHA-256/HMAC
- Hash DRBG KAT
  - i) Self test SHA-1.2 failed, expected [] got []: SHA-1
- Pairwise Consistency Test (PCT) for RSA keypairs
  - i) Consistency test failed: RSA
- Continuous test on DRBG
  - i) Duplicate block detected in DRBG output
- Continuous test on NDRNG
  - i) Duplicate block detected in EntropySource output
- DRBG Health Checks
  - i) Generate
    - Self test SHA-1.1 failed, expected [] got []:  
SHA-1
  - ii) Instantiate
    - Not enough entropy for security strength  
required: SHA-1
  - iii) Reseed
    - Exception on self test: Insufficient entropy  
provided by entropy source: SHA-1

20 All of the above errors result in a critical error state and an administrator must reboot the TOE to run the self tests again by using the appliance's power button. Once the self-tests successfully pass, the appliance will start up successfully. The log messages displaying the error messages can then be viewed via the Syslog viewer.

## 2.4 Updating the TOE

21 Authorized administrators can acquire digitally signed upgrade files from Ixia Technical Support or directly from the Ixia Customer Support Portal from the following location: <https://support.ixiacom.com/software-downloads/43006>



- 22 Follow instructions at [USER] *To upgrade the software on your system* section of the *Appendix C Software Upgrade/Downgrade and Cold Spare Upgrade Procedures* for updating the TOE.
- 23 The TOE verifies the digital signature of the upgrade files using RSA 2048-bit public key. Refer [USER] *Upgrade/Downgrade Guidelines to/from Release 4.5 or Higher/Lower*.

## 3 Configuration Guidance

### 3.1 Installation

24 Follow the instructions of [USER] augmented by the configuration steps in the following sections.

### 3.2 Administration Interfaces

25 Only the following administration interfaces may be used:

- **Console.** Directly connected peripherals via mini USB port, RS-232 (DB9) serial cable, or serial-based RJ-45 port. See [USER] *Craft Port Connection* to connect using serial port.
  - i) Follow instructions at [USER] *Configure the serial (CRAFT) port console* section of the *Government Configuration Guide* chapter to configure session time out and enter an appropriate login banner for the serial console.
  - ii) User may terminate the local session by selecting **Logout** from **Main Menu**. See [USER] *Using the Console Authentication options* section of the *Serial (CRAFT) Port Console Access and Authentication* chapter.
- **HTTPS.** Web based Graphical User Interface via HTTPS.
  - i) Refer [USER] *Government Configuration Guide* chapter to login to the web console as a System Administrator and perform the actions listed in *Common Criteria Required Settings*.
  - ii) User may use the **Logout** button to terminate the current Web Console session.
  - iii) Session termination is supported and may be configured via **System > Settings > Session timeout**. See [USER] *Configure the (Web Console) Session Timeout*.
  - iv) Banner messages are supported and may be configured via **System > Settings > Login banner**. See [USER] *Adding a Login Banner*.
  - v) See [USER] *Configure Server Certificate for Web API Communication* for instructions on configuring certificates and generate signing requests.

26 **NOTE:** The Web API is not interactive and does not display a banner.

### 3.3 Cryptography

27 FIPS mode can be enabled at **System > Settings > FIPS encryption**. Refer [USER] *Enable Server FIPS Encryption*.

### 3.4 Default Passwords

28 **admin.** The default administrator account used to access both serial and web console. On serial, follow instructions at [USER] *Reset Administrator Password* to change the default password. On web console, user will be prompted to change the password on first use. See [USER] *Force Password Change on First Use* section of the *Authentication, Authorization, and Accounting (AAA)* chapter.

**NOTE:** Once an additional administrator account is added, the default administrator account must be modified so that it can only log in to the serial (CRAFT) port console. See [USER] *Configure the default administrator account*.

### 3.5 Setting Time

29 The TOE supports the use of NTP servers which can be accessed via **System > Settings > NTP**. Refer [USER] *Enabling and Configuring NTP Servers*.

### 3.6 Audit Logging

30 The Common Criteria evaluation confirmed that the log events listed at Annex A: Log Reference are generated by the TOE.

31 A syslog must be configured to store the logs as follows:

- To enable, refer to [USER] *Configure Syslog Servers and Adding or Modifying External Syslog Servers* sections.
- Syslog must be used with TLS per the instructions at [USER] *Enabling TLS Encryption* of the *Syslog Support* chapter.

32 The TOE also stores logs locally. See [USER] *How local syslog files work - appending and overwriting files* section of the *About Local Syslog Viewer* chapter for details on overwriting logs.

### 3.7 Administrator Authentication

33 Follow instructions at [USER] *Configure the Web API Service* to configure the number of successive unsuccessful authentication attempts and period of inactivity.

**NOTE:** On the web API, administrator can configure settings for tokens used to authenticate calls to the web API. Refer [USER] *Web console/API settings*.

34 Follow instructions at [USER] *Configure the default administrator account* to disable lockout mechanism at serial console.

35 Refer [USER] *Password Policies* for details about Default Password guidelines and various password policies.

### 3.8 TLS Communication

36 The communication between the Vision NPB system and the syslog server as well as HTTP communications between users and the NPB are protected by TLS encryption. Follow instructions at [USER] *Enabling TLS Encryption* section of the *Syslog Support* chapter to enable TLS communications with a Syslog server. Follow instructions at [ADMIN] *Configure Server Certificate for Web API Communication* to enable TLS over HTTP communications.

37 When a connection is broken, no plaintext is sent. The reconnect re-initiates the TCP handshake and TLS handshake. TLS will be reused when the connection is re-established.

38 TOE supports Subject Alternate Name (SANs) and Common Name (CN) as reference identifiers. When the TLS client receives an X.509 certificate from the server, the client will compare the reference identifier with the established Subject Alternative Names (SANs) in the certificate. If a SAN is available and does not match the reference identifier, then the verification fails, and the channel is

terminated. If there are no SANs of the correct type (DNS name) in the certificate, then the TOE will compare the reference identifier to the Common Name (CN) in the certificate Subject. If there is no CN, then the verification fails and the channel is terminated. If the CN exists and does not match, then the verification fails and the channel is terminated. Otherwise, the reference identifier verification passes and additional verification actions can proceed.

- 39 For Syslog communication, only DNS names are supported as acceptable reference identifiers. IP addresses are not allowed for reference identity.

## Annex A: Log Reference

### 3.9 Format

40 Each audit record includes the following fields:

- Timestamp
- Severity Level (CRITICAL, ALERT, ERROR, WARNING, NOTICE, INFO)
- Message (including user if applicable and indication of success or failure)

41 Refer [USER] *Syslog Message Format* section of the *APPENDIX G NPB Syslog Messages* for more details about format of the logs.

### 3.10 Events

42 The TOE generates the following log events.

**Table 4: Audit Events**

Requirement	Audit Events	Examples
FAU_GEN.1	Start-up and shutdown of the audit functions	<p>Jan 29 08:32:52 10.19.17.10 1 2020-01-29T13:32:52.215Z 10.19.17.10 VisionONE --- 0 AppStack Syslog init complete</p> <p>Jan 29 08:32:53 10.19.17.10 1 2020-01-29T13:32:52.557Z 10.19.17.10 VisionONE --- 1 Syslog server 10.100.0.2 (Port: 514, Facility: LOCAL0, Tls Enabled: false) came on-line</p> <p>Jan 29 08:32:53 10.19.17.10 1 2020-01-29T13:32:52.563Z 10.19.17.10 VisionONE --- 2 System 6322 ready</p> <p>Jan 29 08:32:53 10.19.17.10 1 2020-01-29T13:32:52.564Z 10.19.17.10 VisionONE --- 3 FIPS integrity check completed as of Wed Jan 29 13:29:44 UTC 2020</p> <p>Jan 29 08:32:53 10.19.17.10 1 2020-01-29T13:32:52.564Z 10.19.17.10 VisionONE --- 4 BouncyCastle FIPS selftest completed as of Wed Jan 29 13:29:46 UTC 2020</p> <p>Jan 29 08:32:53 10.19.17.10 1 2020-01-29T13:32:52.564Z 10.19.17.10 VisionONE --- 5 OpenSSL FIPS selftest completed as of Wed Jan 29 13:29:46 UTC 2020</p> <p>Jan 29 08:32:53 10.19.17.10 1 2020-01-29T13:32:52.565Z 10.19.17.10 VisionONE --- 6 FIPS selftest completed successfully of Wed Jan 29 13:29:46 UTC 2020</p> <p>Jan 29 08:32:53 10.19.17.10 1 2020-01-29T13:32:52.592Z 10.19.17.10 VisionONE --- 7 Config.ser read</p>

Requirement	Audit Events	Examples
		<p>Jan 29 08:32:56 10.19.17.10 1 2020-01-29T13:32:56.206Z 10.19.17.10 VisionONE - - - 8 Server ready</p> <p>Jan 22 17:23:02 10.19.17.10 1 2020-01-22T22:23:02.032Z 10.19.17.10 VisionONE - - - 264 "admin" restart system</p> <p>Jan 29 08:25:35 10.19.17.10 1 2020-01-29T13:25:35.512Z 10.19.17.10 VisionONE - - - 1132 Power down system</p>
	Administrative login and logout	<p>Feb 5 12:24:56 10.19.17.10 1 2020-02-05T17:24:56.462Z 10.19.17.10 VisionONE - - - 4731 Successful login Web GUI (ID: testadmin, Source URL: 10.100.1.126, X-Forwarded-Host: WEB_GUI, Token: Token ZmNjM2Y5YWYwNGRINWZINjYwNDNiMzljMWUwN TkWYTNmMWUzYTA4YmI2NTE5ZmVmNmQ0YjhkO TA1ZDQ5Njk4ZA==)</p> <p>Feb 5 12:26:33 10.19.17.10 1 2020-02-05T17:26:33.525Z 10.19.17.10 VisionONE - - - 4734 Session logout Web GUI (ID: testadmin, Source URL: 10.100.1.126, X-Forwarded-Host: WEB_GUI, Token: Token ZmNjM2Y5YWYwNGRINWZINjYwNDNiMzljMWUwN TkWYTNmMWUzYTA4YmI2NTE5ZmVmNmQ0YjhkO TA1ZDQ5Njk4ZA==)</p>
	Changes to TSF data related to configuration changes	<p>Feb 14 08:34:26 10.19.17.10 1 2020-02-14T13:34:26.313Z 10.19.17.10 VisionONE - - - 320 "testadmin" changed System: ENHANCED_SECURITY_SETTINGS=removeTacSh=false, validateCertCrl=true, validateRootCertUse=true, syslogUnknownCert=true, crlServerAddr=, SYSLOG_TLS_HANDSHAKE_ENABLED=true</p>
	Generating/import of, changing, or deleting of cryptographic keys	<p>Jan 9 12:30:15 10.19.17.10 1 2020-01-09T17:30:15.101Z 10.19.17.10 VisionONE - - - 156 "admin" zeroized any existing key pair and created new public/private key pair for TLS</p>
	Resetting passwords	<p>Feb 4 15:02:53 10.19.17.10 1 2020-02-04T20:02:53.596Z 10.19.17.10 VisionONE - - - 2232 "testuser" changed User "testuser": PASSWORD_LAST_CHANGED=Feb 04, 2020 20:02:53 GMT, PASSWORD=****, PASSWORD_HISTORY=****</p>

Requirement	Audit Events	Examples
FCS_HTTPS_EXT.1	Failure to establish a HTTPS Session	Jan 8 11:05:12 10.19.17.10 1 2020-01-08T16:05:15.197Z 10.19.17.10 VisionONE - - - 2154 AppStack "system" "/10.100.1.126:60318" TLS handshake failure. Exception caught: javax.net.ssl.SSLHandshakeException: no cipher suites in common.
FCS_NTP_EXT.1	Configuration of a new time server Removal of configured time server	Feb 5 10:43:11 10.19.17.10 1 2020-02-05T15:43:11.326Z 10.19.17.10 VisionONE - - - 2541 "testadmin" changed System: NTP_SERVER_LIST=Enabled=true [10.19.17.2:123 (Auth Enabled:true, Key Id:100, Key Type: SHA1, Key:****)]
FCS_TLSC_EXT.1	Failure to establish a TLS Session	Jan 29 09:23:32 10.19.17.10 1 2020-01-29T14:23:32.019Z 10.19.17.10 VisionONE - - - 386 Connection has been shutdown: javax.net.ssl.SSLHandshakeException: java.security.cert.CertificateException: No name matching services.example.com found TLS handshake failure.
FCS_TLSS_EXT.1	Failure to establish a TLS Session	Jan 8 11:05:12 10.19.17.10 1 2020-01-08T16:05:15.197Z 10.19.17.10 VisionONE - - - 2154 AppStack "system" "/10.100.1.126:60318" TLS handshake failure. Exception caught: javax.net.ssl.SSLHandshakeException: no cipher suites in common.
FIA_AFL.1	Unsuccessful login attempts limit is met or exceeded.	Jan 14 10:14:30 10.19.17.10 1 2020-01-14T15:14:30.596Z 10.19.17.10 VisionONE - - - 1004 "testadmin" login failed user is locked after a predefined number of consecutive unsuccessful logins or based on a configurable number of days of inactivity where the user has not been logged in, and DoD security policies are enabled
FIA_UIA_EXT.1	All use of identification and authentication mechanism.	Jan 14 15:21:42 10.19.17.10 1 2020-01-14T20:21:42.875Z 10.19.17.10 VisionONE - - - 1266 "test" login failed, 10.100.1.126, invalid user id or password, Session type: Web GUI
FIA_UAU_EXT.2	All use of identification and authentication mechanism.	Jan 14 15:14:14 10.19.17.10 1 2020-01-14T20:14:14.579Z 10.19.17.10 VisionONE - - - 1238 "testuser" login failed, 10.100.1.126, invalid user id or password, Session type: Web GUI  Jan 14 15:14:19 10.19.17.10 1 2020-01-14T20:14:19.239Z 10.19.17.10 VisionONE - - - 1243 Successful login Web GUI (ID: testuser, Source URL: 10.100.1.126, X-Forwarded-Host: WEB_GUI, Token:

Requirement	Audit Events	Examples
		<p>Token  Y2UyYjY3M2QzMGE5MDY0Njc3NzhkOTU2MTRhYzA3ODQ3YzkzY2M0NjZmNDg4YmViZmFmNjM2MmMyYWQ1ODRhYQ==)</p>
FIA_X509_EXT.1/Rev	Unsuccessful attempt to validate a certificate	<p>Broken CA cert chain</p> <p>Jan 29 09:39:17 10.19.17.10 1 2020-01-29T14:39:17.980Z 10.19.17.10 VisionONE - - - 527  Connection has been shutdown:  javax.net.ssl.SSLHandshakeException:  sun.security.validator.ValidatorException: PKIX path building failed:  sun.security.provider.certpath.SunCertPathBuilderException: unable to find valid certification path to requested target TLS handshake failure.</p> <p>Expired CA cert and server cert</p> <p>Jan 29 09:46:26 10.19.17.10 1 2020-01-29T14:46:26.662Z 10.19.17.10 VisionONE - - - 569  Connection has been shutdown:  javax.net.ssl.SSLHandshakeException:  sun.security.validator.ValidatorException: PKIX path validation failed:  java.security.cert.CertPathValidatorException: validity check failed TLS handshake failure.</p> <p>Revoked CA cert and server cert</p> <p>Jan 29 09:52:03 10.19.17.10 1 2020-01-29T14:52:03.285Z 10.19.17.10 VisionONE - - - 600  Connection has been shutdown:  javax.net.ssl.SSLHandshakeException:  sun.security.validator.ValidatorException: PKIX path validation failed:  java.security.cert.CertPathValidatorException: Certificate has been revoked, reason: UNSPECIFIED, revocation date: Thu Jan 09 14:59:31 GMT 2020, authority: CN=Intermediate CA, OU=CC1801, O=Lightship Security, L=Ottawa, ST=ON, C=CA, extension OIDs: [] TLS handshake failure.</p> <p>CA cert without cRLsign bit set</p> <p>Jan 29 10:29:11 10.19.17.10 1 2020-01-29T15:29:11.992Z 10.19.17.10 VisionONE - - - 683  Connection has been shutdown:  javax.net.ssl.SSLHandshakeException:  sun.security.validator.ValidatorException: PKIX path validation failed:</p>



Requirement	Audit Events	Examples
		<p>java.security.cert.CertPathValidatorException: Could not determine revocation status TLS handshake failure.</p> <p>modify any byte in the first eight bytes of the certificate</p> <p>Jan 29 10:34:10 10.19.17.10 1 2020-01-29T15:34:10.617Z 10.19.17.10 VisionONE - - - 712 Connection has been shutdown: javax.net.ssl.SSLProtocolException: Unexpected data detected in stream TLS handshake failure.</p> <p>modify any byte in the last byte of the certificate</p> <p>Jan 29 10:35:38 10.19.17.10 1 2020-01-29T15:35:38.970Z 10.19.17.10 VisionONE - - - 727 Connection has been shutdown: javax.net.ssl.SSLHandshakeException: sun.security.validator.ValidatorException: PKIX path validation failed: java.security.cert.CertPathValidatorException: signature check failed TLS handshake failure.</p> <p>modify any byte in the public key of the certificate</p> <p>Jan 29 10:37:19 10.19.17.10 1 2020-01-29T15:37:19.305Z 10.19.17.10 VisionONE - - - 742 Connection has been shutdown: javax.net.ssl.SSLHandshakeException: sun.security.validator.ValidatorException: PKIX path validation failed: java.security.cert.CertPathValidatorException: java.security.cert.CertificateParsingException: java.io.IOException: subject key, RSA modulus has a small prime factor TLS handshake failure.</p> <p>CA cert without basicConstraints extension</p> <p>Jan 29 10:43:18 10.19.17.10 1 2020-01-29T15:43:18.724Z 10.19.17.10 VisionONE - - - 781 Connection has been shutdown: javax.net.ssl.SSLHandshakeException: sun.security.validator.ValidatorException: PKIX path validation failed: java.security.cert.CertPathValidatorException: basic constraints check failed: this is not a CA certificate TLS handshake failure.</p>

Requirement	Audit Events	Examples
		<p>CA cert without false as CA flag in basicConstraints extension</p> <p>Jan 29 10:44:36 10.19.17.10 1 2020-01-29T15:44:36.879Z 10.19.17.10 VisionONE - - - 796            Connection has been shutdown:            javax.net.ssl.SSLHandshakeException:            sun.security.validator.ValidatorException: PKIX path validation failed:            java.security.cert.CertPathValidatorException: basic constraints check failed: this is not a CA certificate            TLS handshake failure.</p>
FIA_X509_EXT. 2	TOE is unable to verify the validity of the certificate due to network connection problem	<p>Jan 29 10:50:00 10.19.17.10 1 2020-01-29T15:50:00.336Z 10.19.17.10 VisionONE - - - 825            Connection has been shutdown:            javax.net.ssl.SSLHandshakeException:            sun.security.validator.ValidatorException: PKIX path validation failed:            java.security.cert.CertPathValidatorException:            Unable to determine revocation status due to network error TLS handshake failure.</p>
FIA_X509_EXT. 3	Create CSR	<p>Jan 9 12:30:15 10.19.17.10 1 2020-01-09T17:30:15.156Z 10.19.17.10 VisionONE - - - 157            "admin" zeroized any existing key pair and created new public/private key, then created a new certificate signing request (CSR) for TLS</p> <p>Jan 9 13:29:49 10.19.17.10 1 2020-01-09T18:29:49.913Z 10.19.17.10 VisionONE - - - 213            "admin" zeroized any existing key pair and created new public/private key, then created a new certificate signing request (CSR) for Syslog</p> <p>Validating a response message to a Certification Request without a valid certification path results in the function failing</p> <p>Jan 9 13:36:22 10.19.17.10 1 2020-01-09T18:36:22.986Z 10.19.17.10 VisionONE - - - 215            "admin" certificate upload failed for Syslog. No certificate chain found for the certificate in the file.</p> <p>Jan 9 13:38:27 10.19.17.10 1 2020-01-09T18:38:27.175Z 10.19.17.10 VisionONE - - - 216            "admin" certificate upload failed for Syslog. Invalid certificate: Issuer: CN=Root            CA,OU=CC1801,O=Lightship            Security,L=Ottawa,ST=ON,C=CA Serial:            dd323450cef24303. Error: certificate does not verify with supplied key</p> <p>Jan 9 12:39:04 10.19.17.10 1 2020-01-09T17:39:04.203Z 10.19.17.10 VisionONE - - - 167</p>

Requirement	Audit Events	Examples
		"admin" certificate upload failed for TLS. No certificate chain found for the certificate in the file.  Jan 9 12:43:10 10.19.17.10 1 2020-01-09T17:43:10.889Z 10.19.17.10 VisionONE - - - 168 "admin" certificate upload failed for TLS. Invalid certificate: Invalid certificate: Issuer: CN=Root CA,OU=CC1801,O=Lightship Security,L=Ottawa,ST=ON,C=CA Serial: dd323450cef24303. Error: certificate does not verify with supplied key
FMT_MOF.1/ ManualUpdate	Any attempt to initiate a manual update	Jan 29 08:18:08 10.19.17.10 1 2020-01-29T13:18:08.086Z 10.19.17.10 VisionONE - - - 1129 "testadmin" initiated software install using file NVOS-5.3.0.11-73xx-62xx-20200128-144855-5e9315.zip
FMT_MOF.1/ Functions	Modification of the behaviour of the transmission of audit data to an external IT entity, the handling of audit data, the audit functionality when Local Audit Storage Space is full.	Feb 6 08:49:50 10.19.17.10 1 2020-02-06T13:49:50.050Z 10.19.17.10 VisionONE - - - 653 "testadmin" changed System: SYSLOG_SERVER_LIST=[10.100.0.2 (Port: 514, Facility: LOCAL0, Tls Enabled: false), services.example.com (Port: 514, Facility: LOCAL0, Tls Enabled: true)]
FMT_SMF.1	All management activities of TSF data.	Feb 14 08:58:03 10.19.17.11 1 2020-01-31T01:09:10.593Z 10.19.17.11 Vision E40 - - - 157 "admin" changed System: PASSWORD_POLICIES=Enabled ( Type=FIPS_DOD_SECURITY, Expiration days=0, Minimum password length=15, User inactive days=35, Max failures allowed=3, Days to track successful logins=7)
FPT_TUD_EXT. 1	Initiation of update; result of the update attempt (success or failure)	Jan 29 08:18:08 10.19.17.10 1 2020-01-29T13:18:08.086Z 10.19.17.10 VisionONE - - - 1129 "testadmin" initiated software install using file NVOS-5.3.0.11-73xx-62xx-20200128-144855-5e9315.zip  Jan 29 08:46:45 10.19.17.10 1 2020-01-29T13:46:45.290Z 10.19.17.10 VisionONE - - - 170 Software install succeeded
FPT_STM_EXT. 1	Discontinuous changes to time - either Administrator actuated or changed via an	Feb 5 11:07:05 10.19.17.10 1 2020-02-06T00:07:05.454Z 10.19.17.10 VisionONE - - - 2551 System Sync internal clock with NTP server: 10.19.17.2. Time changed from 2020-02-05 16:07:03 GMT to 2020-02-06 00:07:04 GMT

